



Figure B-12. Erosion rill along north slope of CFA-02 Landfill II (PD020605-12).



Figure B-13. Erosion rill on north slope of CFA-02 Landfill II (PD020605-13).



Figure B-14. Erosion rill on northeast slope of CFA-02 Landfill II.




Figure B-15. Institutional control sign at CFA-03 Landfill III (PD020605-23).